

For a thriving New England

CLF Vermont

15 East State Street, Suite 4

Montpelier, VT 05602 P: 802.223.5992 F: 802.223.0060 www.clf.org

June 11, 2013

John Joseph Jalbert, Jr. d/b/a Methuen Motor Mart Co. 102 Hale Street Haverhill, MA 01830

John Joseph Jalbert, Jr., Manager Methuen Motor Mart Co. 469 Merrimack Street Methuen, MA 01844

RECEIVED

JUN 2 4 2013

OFFICE OF THE REGIONAL ADMINISTRATOR

VIA CERTIFIED MAIL, RETURN RECEIPT REQUESTED

RE: Notice of Violations and Intent to File Suit under the Clean Water Act

To Whom It May Concern:

The Conservation Law Foundation ("CLF")¹ hereby gives notice to the addressed persons of its intent to file suit pursuant to Section 505 of the Federal Clean Water Act ("CWA" or "Act"), 33 U.S.C. § 1365(a), for violations of the Act specified below. This letter constitutes notice pursuant to 40 C.F.R., part 135 (the "Notice") to the addressed persons of CLF's intention to file suit in United States District Court of the District of Massachusetts seeking appropriate equitable relief, civil penalties, and other relief no earlier than 60 days from the postmark date of this Notice letter.

The subject of this action is two-fold. First, John Joseph Jalbert, Jr., doing business as Methuen Motor Mart Co. ("Methuen Motor Mart") is discharging stormwater directly associated with the automobile salvage and scrap metal recycling facility located at 469 Merrimack Street Methuen, MA 01844 (the "Facility"), to the waters of the United States without a permit, in violation of 33 U.S.C. §§ 1311(a) and 1342(p)(2)(B). Second, Methuen Motor Mart has failed to obtain coverage under any Clean Water Act permit including the Multi-Sector General Permit²

¹ CLF is a not-for-profit 501(c)(3) organization dedicated to the conservation and protection of New England's environment.

² Environmental Protection Agency, Multi-Sector General Permit for Stormwater Discharges Associated with Industrial Activity (MSGP) [hereinafter MSGP or "permit"], available at http://www.epa.gov/npdes/pubs/msgp2008 finalpermit.pdf (last visited February 13, 2012).



("MSGP") adopted by EPA for industrial sources of polluted stormwater runoff, and failed to comply with the specific requirements of any such permit, in violation of 33 U.S.C. §§ 1342(p)(3)(A) and (p)(4)(A), and 40 C.F.R. §§ 122.26(c)(1) and (e)(1).

BACKGROUND

The Merrimack River segment next to the Facility (Waterbody ID MA84A-04) is within the Merrimack Watershed and flows from the Essex Dam in Lawrence to its confluence with the Little River in Haverhill. The Merrimack River is categorized as a Category 5 Waterbody, indicating that it is impaired or threatened for one or more uses and requiring a TMDL.³ The Merrimack River ultimately discharges into the Atlantic Ocean.

Under the Massachusetts Surface Water Quality law the Merrimack River is a Class SB Waterbody⁴ "designated as a habitat for fish, other aquatic life and wildlife, including for their reproduction, migration, growth and other critical functions, and for primary and secondary contact recreation" and "shall have consistently good aesthetic value." The Merrimack River is also a Class B waterbody⁶ "designated as a habitat for fish, other aquatic life, and wildlife, including for their reproduction, migration, growth and other critical functions, and for primary and secondary contact recreation. Where designated in 314 CMR 4.06, they shall be suitable as a source of public water," "shall be suitable for irrigation and other agricultural uses and for compatible industrial cooling and process uses," and "shall have consistently good aesthetic value. The Merrimack River does not meet these standards and the Environmental Protection Agency ("EPA") has designated the Merrimack River as impaired pursuant to Section 303(d) of the Act for failure to meet minimum water quality standards for a pollutant. The Merrimack River is impaired due to pathogens, polychlorinated biphenyls (PCBs) and nutrients.

http://www.mass.gov/dep/water/resources/tmdls.htm (last visited March 3, 2013).

³ Massachusetts Year 2010 Integrated List of Waters, available at

⁴http://water.epa.gov/scitech/swguidance/standards/wqslibrary/upload/mawqs_figures_tables.pdf (last visited March 3, 2013).

⁵ See Massachusetts Surface Water Quality Standards, 314 MASS. CODE REGS. 4.05:4(b).

⁶Class B for fresh water sections; Class SB in marine sections:

http://water.epa.gov/scitech/swguidance/standards/wqslibrary/upload/mawqs_figures_tables.pdf (last visited March 3, 2013).

⁷ See Massachusetts Surface Water Quality Standards, 314 MASS. CODE REGS. 4.05:3(b).

⁸ See 33 U.S.C. § 1313(d).

http://ofmpub.epa.gov/tmdl_waters10/attains_waterbody.control?p_au_id=MA84A-04&p_cycle=2010&p_state=MA&p_report_type= (last visited June 11, 2013).



Stormwater is water from precipitation events that flows across the ground and pavement after it rains or after snow and ice melt.¹⁰ Industrial activities, such as material handling and storage, processing, reclaiming, and wholesale distribution of junked automobiles, scrap metal, and waste materials or other operations that occur at industrial facilities, may be exposed to stormwater.¹¹ Stormwater from industrial facilities, contaminated with pollutants, is then conveyed into nearby waterbodies.¹²

Methuen Motor Mart is required to apply for coverage under a Clean Water Act discharge permit such as the MSGP in order to discharge lawfully. Since at least 2007, Methuen Motor Mart has been specifically required to apply for coverage under the MSGP by filing a Notice of Intent ("NOI") within 90 days after the initial issuance of the MSGP. On September 29, 2008, after expiration of the prior permit, the EPA issued a new MSGP requiring all covered facilities to file an NOI for coverage under the 2008 permit by January 5, 2009.

Methuen Motor Mart has failed to obtain coverage under the MSGP or any other valid authorization, at any time. Therefore, Methuen Motor Mart is operating in violation of the Clean Water Act.

PERSONS RESPONSIBLE FOR ALLEGED VIOLATIONS

John Joseph Jalbert, Jr., d/b/a Methuen Motor Mart Co., is the person, as defined by 33 U.S.C. § 1362(5), responsible for the violations alleged in this Notice. Methuen Motor Mart and its predecessor, Methuen Motor Mart, Inc., have operated the Facility since at least 2007. Methuen Motor Mart and its agents and directors, including but not limited to John Joseph Jalbert, Jr., have operational control over the day-to-day industrial activities at this Facility. Therefore, they are responsible for managing stormwater at the Facility in compliance with the CWA.

LOCATION OF THE ALLEGED VIOLATION

The violations alleged in this Notice have occurred and continue to occur at the automobile salvage yard and scrap metal recycling Facility located at 469 Merrimack Street Methuen, MA 01844.

¹⁰ See 40 C.F.R. § 122.26(b)(13).

¹¹ See 40 C.F.R. § 122.26(b)(14).

¹² See 58 Fed. Reg. 61,146, 61,154 (November 19, 1993).

¹³ EPA's Final National Pollutant Discharge Elimination System Multi-Sector General Permit for Stormwater Discharges Associated with Industrial Activity (MSGP) was first issued in 1995, reissued in 2000, and again in 2008. *See* 60 Fed. Reg. 50,804 (Sept. 29, 1995); 65 Fed. Reg. 64,746 (Oct. 30, 2000); and 73 Fed. Reg. 56,572 (Sept. 29, 2008). *See* MSGP part 1.1 and 1.3.1.

¹⁴ See MSGP Table 1-2.



ACTIVITIES ALLEGED TO BE VIOLATIONS

Methuen Motor Mart has, and continues to, engage in "industrial activities," and its operations fall under SIC Codes 5015 and 5093, within the meaning of 40 C.F.R. § 122.26(b)(14)(vi). Because the Facility has a primary SIC Code of 5015 and stormwater discharges associated with industrial activity, Methuen Motor Mart is required to apply for, obtain coverage, and comply with the requirements of a National Pollutant Discharge Elimination System ("NPDES") permit such as the MSGP. Methuen Motor Mart has failed to take any of these required steps.

Methuen Motor Mart's, activities at the Facility include, but are not limited to: vehicle dismantling and processing; scrap metal recycling, used parts storage; outdoor vehicle and equipment storage; vehicle and equipment maintenance; vehicle, equipment, and parts washing; and liquid storage. These activities are associated with a wide variety of pollutants, including but not limited to oil and grease; ethylene glycol; heavy metals; mercury; sulfuric acid; galvanized metals; aluminum; petroleum hydrocarbons; suspended solids; arsenic; organics; chlorinated solvents; acid/alkaline wastes; phosphorous; salts; and fuel. The Facility is located on the bank of, and slopes towards, the Merrimack River.

Automobile salvage and scrap metal recycling activities at the Facility are exposed to precipitation and snowmelt. Precipitation falls on and flows over salvage yard and storage areas, picking up pollutants associated with the Facility's operations. The polluted runoff is then flows via site grading, ditches, swales, the operation of gravity, and other conveyances into the Merrimack River, a water of the United States. ¹⁶

STANDARDS AND LIMITATIONS ALLEGED TO HAVE BEEN VIOLATED

The CWA prohibits the discharge of pollutants to the waters of the United States except in accordance with a valid NPDES permit. Methuen Motor Mart discharges stormwater associated with its industrial activity, as defined by 40 C.F.R. § 122.26(b)(14), from its Facility via site grading, ditches, swales, the operation of gravity, and other conveyances into waters of the United States. Because Methuen Motor Mart has not obtained coverage for these stormwater discharges under the MSGP or an individual NPDES permit, it is illegally discharging

¹⁷ 33 U.S.C. § 1311(a).

¹⁵ See MSGP, Appendix D: Activities Covered, at D-4. Automobile salvage yard facilities identified by the SIC Code 5015 and scrap metal recycling facilities identified by SIC Code 5093 are subject to the requirements of the MSGP for stormwater discharges.

¹⁶ See 40 C.F.R. § 122.26(c)(i)(E)(6). EPA has determined that precipitation greater than 0.1 inches in a 24-hour period constitutes a measurable precipitation event for the purposes of evaluating stormwater runoff associated with industrial activity.



stormwater without a permit, in violation of 33 U.S.C. §§ 1311(a) and 1342(p)(2)(B). ¹⁸ By failing to apply for and comply with the specific requirements of the MSGP, Methuen Motor Mart is in violation of 33 U.S.C. §§ 1342(p)(3)(A) and (p)(4)(A), and 40 C.F.R. §§ 122.26(c)(1) and (e)(1).

a. Methuen Motor Mart is discharging stormwater to waters of the United States without a permit.

Methuen Motor Mart is an industrial discharger with a primary SIC Code of 5015 which means that pursuant to Section 402(p) of the Act, Methuen Motor Mart is obligated to apply for coverage under the MSGP or obtain other legal authorization. Because Methuen Motor Mart has operated and continues to operate without a permit under Section 402(p), Methuen Motor Mart is in violation of Section 301(a) of the Act.

In addition, during storm events, Methuen Motor Mart's "industrial activities" at its Facility have resulted in a "discharge of pollutants" within the meaning of 33 U.S.C. § 1362(12) and "stormwater discharge associated with industrial activity" within the meaning of 40 C.F.R. § 122.26(b)(14), from its Facility on each and every day that there has been a measurable precipitation event of above 0.1 inches. There have been many such storm events since 2007. The Facility is generating and conveying pollutants from at least the following "point sources" – vehicles and equipment left outdoors, the vehicles driving on and off the Facility, channels, ditches, discrete fissures, containers and other conveyances to Merrimack River. ¹⁹ The Merrimack River segment next to the Facility (Waterbody ID MA84A-04) and downstream segments are "waters of the United States," as defined in 40 C.F.R. § 122.2, and therefore, "navigable waters," as defined in 33 U.S.C. § 1362(7). The Facility is discharging this industrial stormwater without the permit required under Section 402 of the Act, 33 U.S.C. § 1342.

b. Methuen Motor Mart is violating the Clean Water Act by failing to obtain coverage and failing to comply with the requirements of the MSGP.

Methuen Motor Mart is violating 33 U.S.C. §§ 1342(p)(3)(A) and (p)(4)(A), and 40 C.F.R. §§ 122.26(c)(1) and (e)(1), by failing to apply for, obtain coverage, and comply with the requirements of the MSGP.²⁰ The Facility at address has a primary SIC Code of 5015 and must obtain coverage under the MSGP for its stormwater discharges and for stormwater discharges from any co-located industrial activities (including scrap metal recycling activities under SIC

¹⁸ See 33 U.S.C. § 1362(12); 40 C.F.R. § 122.2; MSGP, Appendix A: Definitions, Abbreviations, and Acronyms (defining the term "discharge of a pollutant" as "any addition of any pollutant to navigable waters from any point source").

¹⁹ These discharges constitute "point sources" as defined by 33 U.S.C. § 1362(14) and 40 C.F.R. § 122.2. ²⁰ MSGP part 1.1 and 1.2.



Code 5093).²¹ Methuen Motor Mart's failure to obtain coverage and comply with the permit is in violation of the MSGP and 33 U.S.C. § 1342(p) of the Clean Water Act. ²²

1) Methuen Motor Mart Must Develop and Implement a Stormwater Pollution Prevention Plan (SWPPP).

As a prerequisite to obtaining coverage under the MSGP, Methuen Motor Mart must prepare a Stormwater Pollution Prevention Plan ("SWPPP").²³ The SWPPP must include, but is not limited to, the following: information related to a company stormwater pollution prevention team, a site description, a summary of pollutant sources, a description of control measures, and schedules and procedures pertaining to control measures and monitoring.²⁴ Methuen Motor Mart has failed to develop a SWPPP in accordance with the MSGP requirements in violation of the MSGP and the Clean Water Act, 33 U.S.C. § 1342(p).

2) Methuen Motor Mart, Must Submit to EPA a Complete Notice of Intent to be Covered under the MSGP.

To be eligible to discharge under the MSGP, Methuen Motor Mart must submit a complete Notice of Intent ("NOI") to the EPA.²⁵ To complete the NOI, Methuen Motor Mart, is required to determine whether the body of water the stormwater is discharged to is an "impaired" water body, and whether the Facility discharges any specific pollutants listed on the NOI to that water body.²⁶ The Merrimack River is classified as "impaired" water.²⁷ Because Methuen Motor Mart is a "New Discharger" under the MSGP,²⁸ it must also provide data and other technical information to EPA to discharge to impaired waters,²⁹ as well as implement and maintain any control measures or conditions to meet applicable water quality standards.³⁰ Additionally, as part of preparing the NOI, the covered Facility must make certain verifications such as verifying that

²¹ See MSGP part 1.1; MSGP part 8.M.

²² A thorough search of EPA's Electronic Stormwater Notice of Intent database reveals that Methuen Motor Mart has not filed an NOI for the Facility. EPA's Electronic Stormwater Notice of Intent database, http://cfpub.epa.gov/npdes/stormwater/noi/noisearch.cfm (last visited May 22, 2013).

²³ See MSGP part 5.

²⁴ See MSGP part 5.1.

²⁵ See MSGP part 1.3.1.

²⁶ See MSGP part 2.2.2.

²⁷ See supra pp. 2–3.

²⁸ See MSGP, Appendix A: Definitions, Abbreviations, and Acronyms, at A-4 (defining the term "new discharger" as "a facility from which there is a discharge, that did not commence the discharge at a particular site prior to August 13, 1979, which is not a new source, and which has never received a finally effective NPDES permit for discharges at that site"); see also 40 C.F.R. § 122.2.

²⁹ See MSGP part 1.1.4.7.

³⁰ See MSGP part 2.2.2.3.



no harm is done to a species in violation of the Endangered Species Act.³¹ Methuen Motor Mart has failed to prepare and file an NOI meeting all applicable requirements in violation of the MSGP and the Clean Water Act, 33 U.S.C. § 1342(p).

3) Methuen Motor Mart Must Take Control Measures and Meet Water-Quality Effluent Limitations.

To be eligible to discharge under the MSGP, Methuen Motor Mart must select, design, install, and implement control measures (including best management practices) to prevent polluted stormwater discharges from reaching nearby waterbodies. Methuen Motor Mart must address the selection and design considerations in the permit, meet the non-numeric effluent limitations in the permit, and meet limits contained in applicable permit effluent limitations guidelines.³² These control practices must be in accordance with good engineering practices and manufacturer's specifications.³³ If the control measures are not achieving their intended effect of minimizing pollutant discharges, the permittee must modify these control measures as expeditiously as practicable.³⁴ Methuen Motor Mart has failed to cover the materials and operations that may result in polluted stormwater runoff. Methuen Motor Mart has not implemented the required control measures in violation of the MSGP and the Clean Water Act, 33 U.S.C. § 1342(p).

4) Methuen Motor Mart Must Conduct Routine Facility Inspections.

To be eligible to discharge under the MSGP, Methuen Motor Mart must conduct routine inspections of all areas of the Facility where industrial materials or activities are exposed to precipitation, and must ensure that all stormwater control measures comply with the effluent limits contained in the MSGP.³⁵ Routine inspections must be conducted at least quarterly but in many instances monthly inspections are most appropriate.³⁶ These inspections must occur when the Facility is in operation.³⁷ The schedule of these inspections must be included in the Facility's SWPPP and be performed by qualified personnel.³⁸ Methuen Motor Mart has failed to conduct the required routine inspections in accordance with the MSGP requirements in violation of the MSGP and the Clean Water Act, 33 U.S.C. § 1342(p).

5) Methuen Motor Mart, Must Comply with the Required Monitoring and Sampling Procedures.

 ³¹ See MSGP part 1.1.4.5 and 2.3.
32 See MSGP part 2.1.

³³ *Id*.

³⁴ *Id*.

³⁵ See MSGP part 4.1.

³⁶ *Id*.

³⁷ *Id*.

³⁸ *Id*.



To be eligible to discharge under the MSGP, Methuen Motor Mart must collect and analyze stormwater samples and document monitoring activities consistent with the procedures in the MSGP.³⁹ The MSGP requires five types of analytical monitoring (one or more of which may apply) including quarterly benchmark monitoring, annual effluent limitations guidelines monitoring, State or Tribal-specific monitoring, impaired waters monitoring, and other monitoring as required by the EPA.⁴⁰ An operator must monitor each outfall identified in the SWPPP covered by a numeric effluent limit.⁴¹ Required monitoring must be performed after stormwater events that result in an actual discharge on a required schedule.⁴² All monitoring data collected under the Permit must be reported to EPA. Furthermore, because the Merrimack River is an "impaired water" under 33 U.S.C. § 1313(d), Methuen Motor Mart must monitor for all pollutants for which the Merrimack River is impaired.⁴³ Methuen Motor Mart has failed to conduct the required monitoring under the MSGP and has failed to submit the required monitoring reports to EPA in violation of the MSGP and the Clean Water Act, 33 U.S.C. § 1342(p).

6) Methuen Motor Mart Must Carry out the Required Reporting and Recordkeeping.

Methuen Motor Mart must maintain and submit any and all required monitoring data.⁴⁴ Such monitoring data includes the following: an annual report to EPA which includes the Facility's findings from the annual comprehensive site inspection and any documentation of correction actions;⁴⁵ an Exceedance Report to the EPA if any of the follow-up monitoring shows any exceedances of a numeric effluent limit;⁴⁶ and any other required reports under the MSGP.⁴⁷ Methuen Motor Mart has failed to maintain the required records and failed to submit all required monitoring data under the MSGP in violation of the MSGP and the Clean Water Act, 33 U.S.C. § 1342(p).

³⁹ See MSGP part 6.

⁴⁰ See MSGP part 6.2.

⁴¹ See MSGP part 6.1.1.

⁴² See MSGP part 6.1.3.

⁴³ See MSGP part 6.2.4.

⁴⁴ See MSGP part 7.1

⁴⁵ See MSGP part 7.2.

⁴⁶ See MSGP part 7.3.

⁴⁷ See MSGP part 7.4.



7) Methuen Motor Mart Must Comply with the Requirement of MSGP Subpart M.

Methuen Motor Mart must also comply with the sector-specific requirements contained in Subpart M of the MSGP.⁴⁸ Subpart M requires automobile salvage yard facilities to implement additional technology-based effluent limits,⁴⁹ meet additional SWPPP and inspection requirements,⁵⁰ and monitor stormwater discharges for compliance with the benchmark limitations applicable specifically to automobile salvage yard facilities.⁵¹ Methuen Motor Mart has failed to comply with the requirements of Subpart M of the MSGP in violation of the MSGP and the Clean Water Act, 33 U.S.C. § 1342(p).

DATES OF VIOLATION

Each day on which Methuen Motor Mart operates its Facility without permit coverage or discharges stormwater without a permit from the Facility is a separate and distinct violation of Section 301(a) and 402(p)(2)(B) of the CWA, 33 U.S.C. §§ 1311(a) and 1342(p)(2)(B).

Methuen Motor Mart Co. and its predecessor, Methuen Motor Mart, Inc., has discharged stormwater without a permit in violation of Section 301(a) of the CWA, 33 U.S.C. § 1311(a), on every day since at least 2007 on which there has been a measurable precipitation event.

Every day, since at least 2007, on which Methuen Motor Mart has failed and continues to fail to apply for, obtain coverage under, and comply with the requirements of the MSGP is a violation of Section 402(p)(3)(A) and (p)(4)(A) of the CWA, 33 U.S.C. §§ 1342(p)(3)(A) and (p)(4)(A).

These violations are ongoing and continuous, and barring a change in the stormwater management controls at the Facility and full compliance with the permitting requirements of the Clean Water Act, these violations will continue indefinitely.

RELIEF REQUESTED

Methuen Motor Mart is liable for the above-described violations occurring prior to the date of this letter, and for every day that these violations continue. Pursuant to Section 309(d) of the Act, 33 U.S.C. § 1319(d), and the Adjustment of Civil Monetary Penalties for Inflation, 40 C.F.R. § 19.4, each separate violation of the Act subjects Methuen Motor Mart to a penalty up to \$32,500 per day for each violation which occurred between March 15, 2004 and January 12,

⁴⁹ See MSGP part 8.M.2.

⁵¹ See MSGP 8.M.5.

⁴⁸ See MSGP, Appendix D, Table D-1, Sector M.

⁵⁰ See MSGP part 8.M.3 and 8.M.4.



2009, and up to \$37,500 per day for each violation that occurred after January 12, 2009.⁵² CLF will seek the full penalties allowed by law.

In addition to civil penalties, CLF will seek declaratory relief and injunctive relief to prevent further violations of the Clean Water Act pursuant to Sections 505(a) and (d), 33 U.S.C. § 1365(a) and (d), and such other relief as permitted by law. CLF will seek an order from the Court requiring Methuen Motor Mart to correct all identified violations through direct implementation of control measures and demonstration of full regulatory compliance.

Lastly, pursuant to Section 505(d) of the Act, 33 U.S.C. § 1365(d), CLF will seek recovery of costs and fees associated with matter.

CONCLUSION

During the 60-day notice period, CLF is willing to discuss effective remedies for the violations noted in this letter that may avoid the necessity of further litigation. If you wish to pursue such discussions, please have your attorney contact Zachary Griefen within the next 20 days so that negotiations may be completed before the end of the 60-day notice period. We do not intend to delay the filing of a complaint in federal court if discussions are continuing at the conclusion of the 60 days.

Sincerely,

Zachary K. Griefen, Esq.

Conservation Law Foundation 15 East State Street, Suite 4

Montpelier, VT 05602

(802) 223-5992 x4011

zgriefen@clf.org

⁵² 40 C.F.R. § 19.2



cc:

Lisa Jackson Administrator Environmental Protection Agency Ariel Rios Building 1200 Pennsylvania Avenue, N.W. Washington, DC 20460

H. Curtis Spalding Environmental Protection Agency EPA Region 1 Administrator 5 Post Office Square - Suite 100 Boston, MA 02109-3912

Kenneth L. Kimmell, Commissioner Massachusetts Department of Environmental Protection One Winter Street Boston, MA 02108

	•